

Menu

HISTORY FILE MAP for year 2006


REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

042.17:00-17:11 11m realtime 1024 bps plus 2h33m playback 512 bps data lost as
(041.17:58-20:31) DSS-43 antenna stopped tracking in elevation. DR C104768 refers.



044.05:00-05:11 & 044.05:47-06:33 11m + 46m realtime 1024 bps lost. DSS-24 unable to calibrate transmitter above 5KW on Day 43, therefore uplink lost, and uplink on D044 performed using DSS-14 arranged with DSN and Cassini. Realtime data lost due to availability conflicting with scheduled uplink time in the first instance, and turnaround of stations between spacecraft in the second. DR G106529 refers.